

Inhaltsverzeichnis

5 Working with NX	3
5.1 Creating items in Teamcenter	3
5.2 Preparation	4
5.3 Create Items with the help of NX	4
5.4 Revision and save parts	5
5.5 Teamcenter Navigator	6
5.6 Teamcenter Navigator Search	7
5.7 Teamcenter Navigator Advanced Search	9
5.8 Teamcenter functions in the assembly Navigator	9
5.9 Creation of a UGParts (drawing)	10
5.9.1 NX TOOLS - Loading the drawing frame	11
5.9.2 NX TOOLS - Creating a drawing sheet	12
5.9.3 NX TOOLS - Change drawing frame / format on existing drawing	13
5.9.4 NX TOOLS - Change drawing frame / format on existing drawing	15


5 Working with NX

5.1 Creating items in Teamcenter

Create a new part in Teamcenter as usual:

Select „File→New→Item“ and select the type  FFG Engineering Item.

Assign an item ID and assign a (temporary) name.




Choose a name from the naming catalog.

Unit of Measure = Empty (each)

Press „Next“.

Enter the essential master data.



Erstellungsinformationen für Geschäftsobjekt definieren

Erstellungsinformationen für Geschäftsobjekt definieren

FFG Engineering Item

Release Information

Tragen Sie hier die für eine Freigabe der Revision notwendigen Informationen ein.
Enter the information required to release a revision.

Produkt: Beschaffungsart:

CS: Q-Code:

< Zurück Weiter > Abschließen Schließen


Press „Finish“. Then select the newly created item or item revision and start NX via  in the menu bar. Once you save the part file in NX, the dataset (UGMaster) is placed under the Item Revision.

5.2 Preparation

Before you start working in NX, please first load the role „FFG Standard“ via the sidebar .


5.3 Create Items with the help of NX

- The creation of a new item in Teamcenter is performed in NX as follows:



1. Create a new data record via file → New...
2. Create a new record via Ctrl+N


- The creation of a new item as master part is visible as relationship „master“ and contains the model.
- The creation of a new non-master part is visible as relationship „specification“ and contains the DrawingPart.



Here, certain mandatory attributes must be assigned to the newly created item.

5.4 Revision and save parts

- The revision of **Master parts** is also carried out: Menu File → Save → Save as...
- Create as new change status (revision)
- Save as new element creates a new part under a new part number
- Save as Alt-Rep creates a new dataset with altern. Geometry presentation under the current part / revision master.




1. Save as action - New element / New change status
2. Double-click to assign a new revision number to the Item Revision.


- If an item revision contains dependent files in addition to the **Master part**, the documents to be transferred can be selected if this is defined in the preferences.

5.5 Teamcenter Navigator

- The Teamcenter Navigator shows the current folder structure of the user.
- The columns can be adjusted as required.



- The following file operations are possible with RMT:



1. Cut and Copy has the same effect as in the „My Teamcenter“ environment
2. Opens the „Add Component“ dialog
3. Add the object to a project

5.6 Teamcenter Navigator Search

☐ Teamcenter Navigator

View Style

Tree

Object	Number	Revision	Description	Type	Checke...	Statuses	Date Modifi
+ Newstuff			jdoe	Newstuff Fol...			27-Aug-2
- Testbaugruppen				Folder			06-Aug-2
+ X.0000.3311...	X.0000.3311			FFG Engineeri...			18-Jul-20
+ X.0000.3763...	X.0000.3763			FFG Engineeri...			25-Jul-20
+ X.0000.3908...	X.0000.3908			FFG Engineeri...			25-Jul-20
+ X.0000.3936...	X.0000.3936			FFG Engineeri...			01-Aug-2
+ X.0000.3958...	X.0000.3958			FFG Engineeri...			02-Aug-2
+ X.0000.3978...	X.0000.3978			FFG Engineeri...			26-Jul-20
+ X.0000.9515...	X.0000.9515			FFG Engineeri...			23-Aug-2
+ X.0001.8631...	X.0001.8631			FFG Engineeri...			15-Aug-2
+ X.0001.8972...	X.0001.8972			FFG Engineeri...			02-Aug-2
+ X.0001.8973...	X.0001.8973			FFG Engineeri...			08-Aug-2
+ X.0004.4123...	X.0004.4123			FFG Engineeri...			06-Aug-2
+ Use Cases				Folder			29-Jul-20
+ X.0003.0032 M...	X.0003.0032			FFG Engineeri...			27-Aug-2
- X.0004.7713 CO...	X.0004.7713			FFG Engineeri...			27-Aug-2

Search

X.000*

Advanced Search...

Browse Filter

Detail Level

Full

Revision

All

Type

All

Assembly Load Options

☐ Load Structure Only

Option


Partially Load

Revision Rule/Configuration Context

Latest Working

Load Options Dialog

Preview




1. Search Wildcards as in Teamcenter area
2. Advanced Search
3. Loading options for assemblies

5.7 Teamcenter Navigator Advanced Search

1. Search criteria
2. Look for it:
3. Display last searches
4. ...Searches saved in „My Teamcenter“


5.8 Teamcenter functions in the assembly Navigator

- Keep all Teamcenter information up to date



5.9 Creation of a UGParts (drawing)

To create a UGPart in Teamcenter, please load the part or assembly from Teamcenter to NX. Then create the UGPart belonging to the UGMaster via File → New (Ctrl+N).



Then select the register „FFG Drawing“ and the corresponding seedpart „FFG-nx120_mag_drawing“. The corresponding attributes are taken from the item revision. Confirm this with OK.

New

FFG Model

FFG Drawing

Templates

Units

Millimeters

Name	Type	Units
FFG - nx120_mag_drawing	Drawing	Millimeters
FFG - nx120_mag_drawing (no MM)	Drawing	Millimeters
Blank	Drawing	Millimeters

Preview

No preview available

Name and Attributes

Name	Value	Other Parameters
1 ID	X.0001.8631	
2 Name	MULTI SPINDLE HEAD	
3 Material Type	HALB	
4 Dataset Name	X.0001.8631-00	

Secondary Attributes

Reference Part

Number

X.0001.8631

Revision

00

Name

X.0001.8631-00

Browse...




OK

Cancel

5.9.1 NX TOOLS - Loading the drawing frame





Proceed as follows to add the drawing frame and sheet format:

1. Overview - Frame functions	
	Zeichnungsrahmen laden Teamcenter-Informationen aktualisieren Abbild aktualisieren
2. Load drawing frame	
	Zeichnungsrahmen laden
3. Drawing frame on Sheet 1	

	
4. Selection of the desired frame	
	
5. Selection of the drawing format	
	

5.9.2 NX TOOLS - Creating a drawing sheet


1. Overview - Frame functions	
	 Zeichnungrahmen laden  Teamcenter-Informationen aktualisieren  Abbild aktualisieren
2. Load drawing frame	
	 Zeichnungrahmen laden
3. Drawing frame on Sheet 1	

	
4.	Selection of the desired frame
	
5.	Selection of the drawing format
	
6.	Accept naming of Sheet n
	

5.9.3 NX TOOLS - Change drawing frame / format on existing drawing

1.	Overview - Frame functions
	 Zeichnungrahmen laden  Teamcenter-Informationen aktualisieren  Abbild aktualisieren

2. Load drawing frame	 Zeichnungrahmen laden
3. Drawing frame on Sheet 1	New frame on Sheet 1 Create new drawing with frame. OK Back Cancel
4. Selection of the desired frame	CorCom Hessapp MAG Modul WuF Kunde -- No more data -- OK Back Cancel
5. Selection of the drawing format	DIN A0 TC DIN A1 TC DIN A2 TC DIN A3 TC -- No more data -- OK Back Cancel
6. Delete all patterns	



5.9.4 NX TOOLS - Change drawing frame / format on existing drawing

 Teamcenter-Informationen aktualisieren	Transfer metadata from Teamcenter to NX
 Abbild aktualisieren	Manual update of metadata in the text header